

BUILDING SAFETY CERTIFICATE

No: _____

Date: 14-08-2023

1. Certified that the ARMY PUBLIC SCHOOL BIRPUR, Garhi Cantt, Dehradun comprised of _____ Single story buildings (Senior Secondary, Secondary & Primary Wing including offices and staff rooms).

2. Buildings are inspected by me on ground on 14-08-2023 and found structurally sound for class rooms including staff rooms and offices etc and their stability will not be endangered by their use. Building No P-11, P-12, P-13, P-14, T-48, T-98, T-99, T-47, T-40, T-50, T-1, T-2, T-3, T-4, T-6 and P-6.

This certificate is valid upto one year.

1. All buildings required Minor Repair.

2. Bldg No - P-50, P-22 require spl. Repair. (cracks are observed in these bldgs)

Sumar
JE(BRS)


AGEB/R-II

Signature with seal: _____

Name: _____

Designation: _____

Date: 14-08-2023

(Anjali Tyagi)

Maj

Garrison Engineer

To

The Principal
Army Public School Birpur
Garhi Cantt, Dehradun

(Name and Address of the Institution)