

BUILDING SAFETY CERTIFICATE

No : _____


Date : 21 Oct 2020


Certified that the **ARMY PUBLIC SCHOOL BIRPUR, Garhi Cantt, Dehradun** comprised of..... Single storey buildings (Senior Secondary, Secondary & Primary Wing including offices and staff rooms).

Buildings are inspected by me on ground on 21 Oct 2020 and found structurally sound for class rooms including staff rooms and offices etc and their stability will not be endangered by their use.

Build. No: P-11, P-12, P-13, P-14, T-48, T-98, T-99, T-47, T-46, P-22, T-50, T-51,

This certificate is valid upto one year..... T-1, T-2, T-3, T-4, T-6, P-6



AGEBLR


Signature with Seal : _____
Name: (Manish Yadav, IDSE)
Designation : EE (SG)
Garrison Engineer
Dated : 21/10/20

To

**The Principal
Army Public School Birpur
Garhi Cantt, Dehradun**

(Name & Address of the Institution)


Principal
Army Public School, Birpur
Dehradun (U.K.)